








Choosing Greener Plastics

When heating / sanding

Wear a respirator + Have good ventilation

GOOD FOR:

-  Eating / Drinking
-  Laser-cutting
-  Casting
-  Strength
-  Bearing Surface

PLA = polylactic acid bioplastic
 PHA = Polyhydroxyalkanoate bioplastic
 HDPE = high-density polyethylene
 PET = polyethylene terephthalate
 LDPE = low-density polyethylene
 PP = polypropylene
 PMMA = acrylic
 PU = polyurethane
 PS = polystyrene
 ABS = acrylonitrile butadiene styrene
 PC = polycarbonate
 PVC = polyvinyl chloride

